



Date: 15 May 2015

Product Affected:

8503
8503AF
8503AFS
CX1140LD
CX1140LDS
CX1154E
CX1175B
CX1573A/2
CX2800
FX12A
FX2522
FX2533
HX3025

Product Replacement:

For recommendations of replacement products, please contact your local sales representative. Alternatively, please submit any enquiries via the e2v website (www.e2v.com/contact-us/)

Reason for Discontinuance:

As part of e2v's ongoing review of its product portfolio, the affected products have been identified for obsolescence.

Last Time Buy Date:

Not applicable.

Last Ship Date:

Not applicable.

Responses and queries:

No response is required to this notification.

Warranty:

e2v will make provision for warranty to cover all product supplied in the last 2 years.

Repairs:

Repairs may be performed within the warranty period, and beyond that subject to the terms and conditions of contract entered.

This Information is provided solely in connection with the affected products described above. The supply of the Affected Product(s) shall be subject to e2v's General Terms and Conditions of Sale or any specific contractual terms agreed in writing between the parties. All warranties, conditions and other terms implied by statute or common law are excluded to the fullest extent permitted by law.